#### **Groundwater Monitoring Points In the Upper Little Ouse Valley**

The following is a summary of known groundwater monitoring points in the headwaters area as of July 2013. It includes those installed by EA, SWT and LOHP. Grid references and photos were taken of all points and they are mapped as accurately as possible on the following maps. EA references numbers ("WISKI") are provided where known. These are often shown on site. There is no stratigraphy available or information on which layer some of the EA piezometers are recording – EA should have this information. Nor is it known which of the following are being recorded or by whom.

Most of the EA assemblies have steel caps and padlocks.

For existing tubes, two NGRs are given; that supplied by EA and that recorded in the field by MH on 30 May 2013 using a hand held Garmin GPS unit. Both are given as the GPS has given slightly different readings.

This was compiled by Mike Harding from information supplied by EA and Peter Frizzell (who installed new shallow dipwells and gauge boards for LOHP in June 2013).

#### **Blo' Norton Fen**

Photo	Мар	Reference	NGR	Comments
No.	No.	No.		
1	1	TM07/258a	TM 02008 78955 (EA)	Middle of fen. Recording layer not
		TM07/258b	TM 02005 78963 (MH)	known. Includes Datum post
2 & 3	1	TM07/166	TM 02068 78935 (EA)	In private field next to fen. Marked
		TM07/167	TM 02081 78923 (MH)	by red & white post. Two tubes
				within concrete apron under steel
				flaps, no caps. No indication which is
				which or the layers recorded.

Map 1: Blo' Norton, Thelnetham Old Fen, Thelnetham Middle Fen and Webb's Fen.




Photo 1: Blo Norton Fen TM07/ 258a and 258b



Photo 2 and 3: Blo Norton Fen, TM07/166 and TM07/167. No indication on site as to which tube is which.





#### **Thelnetham Old Fen**

**NOTE:** EA dipwells TM07/242 and TM07/243 could not be re-found. The NGR given of TM 01889 78790 placed the dipwells in the middle of the alder carr. It is possible that the GPS cords supplied are incorrect and that these two dipwells are the same as the grey SWT dipwells with photo no. 9.

Photo	Мар	Reference	NGR	Comments
No.	No.	No.		
4 & 5	1	TM07/248	TM 01959 78850 (EA)	River gaugeboard with automatic
			TM 01940 78856 (MH)	recorder adjacent.
6	1	TM07/247	TM 01990 78810 (EA)	Gaugeboard in ditch between Old
			TM 01997 78824 (MH)	fen and private land. Ditch dry.
7	1	TM07/246	TM 01958 78819 (EA)	By the path in Old Fen.
			TM 01976 78778 (MH)	
8	1	TM07/257a	TM 01924 78718 (EA)	Middle of Old Fen
		TM07/257b	TM 01923 78728 (MH)	
9	1	TOF 1	TM 01913 78707 (MH)	Grey pipe dipwells with datum post.
				Installed by SWT. New reference
				number. Possibly the missing EA
				dipwells 242 and 243?
10 &	1	TM07/245	TM 01818 78630 (EA)	Cluster of 3 pipes. Water was heard
11		TM07/244	TM 01821 78634 (MH)	bubbling up pipe 244 on 30/05/13,
		TM07/252		with water overflowing through hole
				15cm above ground level. Suggests
				groundwater rising under artesian
				pressure, well above ground surface.

Photos 4 and 5 :TM07/248 Little Ouse Stageboard with automatic recorder, between Old Fen and Blo' Norton Fen.





Photo 6: TM07/247. Ditch between Old Fen and Private Land.



Photo 7: TM07/246. Old Fen



Photo 8: TM07/257a and TM07/257b, in the centre of Old Fen



Photo 9: TOF 1 SWT Dipwells. No EA reference. Centre of Old Fen.



Photo 10: TM07/245, TM07/244, TM07/252 Margin of Old Fen.



Photo 11: Near to ground level of TM07/244. Water rising in tube and leaking out.



### **Middle Fen**

Note that TM07/240 and TM07/241 were not found. EA's GPS coordinates (TM 01466 78722) put them bear to TM07/256a/b, in the fen vegetation of Middle Fen, but no trace could be found. There used to be grey dipwell tubes much like Photo 9, but these were absent – perhaps the lost dipwells?

Photo	Мар	Reference	NGR	Comments
No.	No.	No.		
12	1	TM07/256a	TM 01472 78725 (EA)	Paired dipwells in the middle of
		TM07/256b	TM 01469 78733 (MH)	Middle Fen
13	1	TM07/249	TM 01622 78839 (EA)	Near to the path.
			TM01616 78844 (MH)	
14	1	TM07/250	TM 01614 78834 (EA)	Stage board and recorder in ditch
			TM 01606 78842 (MH)	between Middle Fen and private
				land

Photo 12: TM07/256a and TM07/256b, middle of Middle Fen



Photo 13: TM07/249. Near to the path, Middle Fen



Photo 14: TM07/250. Boundary Ditch between Middle Fen and Private Land



# Parker-Bleyswyck's

Photo	Мар	Reference	NGR	Comments
No.	No.	No.		
15	2	P1	TM 01314 78955 (MH)	Parker's Piece. Black pipe dipwell in
				exclosure near trees on raised
				margin.
16	2	B1	TM 01535 78947 (MH)	Bleyswyck's Bank. Black pipe dipwell
				in exclosure on margin.
17	2	P2	TM 01316 78791 (PF)	Scrape in Parkers Piece. Stageboard.
18	2	P3	TM 01323 79037 (PF)	River Gaugeboard.

Map 2: Parkers-Bleywyck's and Nearby




Photo 15: Parkers Piece, P1.



Photo 16: Bleyswyck's Bank, B1.




Photo 17: Parkers Piece, P2.



Photo 18: Parkers Piece, P3.



### **Broomscot Common**

Photo	Мар	Reference	NGR	Comments
No.	No.	No.		
19	3	B1	TM 00427 80785 (PF)	Dipwell in fen north of the drain
20	3	B2	TM 00428 80775 (PF)	Stageboard in stream

**Map 3 Broomscot Common** 





Photo 19: Broomscot Common, B1.







Webbs Fen

Photo	Мар	Reference	NGR	Comments
No.	No.	No.		
21	1	W1		Dipwell adjacent to the new scrape,
			TM 01718 78883 (PF)	east side.
22	1	W2	TM 01696 78812 (PF)	Dipwell in the middle of the field.
23	1	W3	TM 01670 78706 (PF)	Dipwell near to the gate.
24	1	W4	TM 01723 78979 (PF)	Stageboard in the river

Photo 21: Webbs Fen, W1



Photo 22: Webbs Fen, W2



Photo 23: Webbs Fen, W3



Photo 24: Webbs Fen, W4



# **Scarfe Meadows**

Photo	Мар	Reference	NGR	Comments
No.	No.	No.		
25	4	S1		Gaugeboard in the main east-west
			TL 99732 80835 (PF)	drain
26	4	S2		Gaugeboard in the north-south
			TL 99757 80754 (PF)	middle drain
27	4	S3	TL 99693 80703 (PF)	Gaugeboard in the river

Map 4 : Scarfe Meadows




Photo 25: Scarfe Meadows, S1



Photo 26: Scarfe Meadows, S2



Photo 27: Scarfe Meadows, S3



# **Others**

Photo	Мар	Reference	NGR	Comments
No.	No.	No.		
28	2	TM07/259A	TM 01492 79174 (EA)	Row of three casings on private
		TM07/259B		meadow west of Blo' Norton Fen,
		TM07/259C		next to Fen Road.

Photo 28: TM07/259A, TM07/259B, TM07/259C. Private meadow next to Fen Road.

